

CUSTOMER		PART NUMBER		REV		CONSTRUCTION										SCHEMATIC DRAWING	
CONEXANT		CTX603001A															
BOBBIN:		BS-504-03														SCHEMATIC DRAWING	
CORE:		TR-003/01-01		A-250254												BOTTOM VIEW PIN LOCATION	
GAP:		X															
TAPE:		X															
ASSEMBLY: CORE 組合後先纏腳焊錫, 再於 BASE 上塗二支 GL-014 膠, 烘乾固定																	
FRAME(CLIP):		X															
PIN#1 INDICATOR:		黑印在 BASE 上															
TAP WID Mm	TAP LYR	WID	STR	END	CW/ CCW	WIR SIZ	COA	TUR	CRE PAG	DEN LSN	SIDE WALL	REMARKS					
		W1	1	2	順	0.1	1.5	15	X	1.5	X	1. CORE 纏腳時, 須於 CAN 上至少纏 4 圈以上, 且纏線要平整靠齊					
		W2	4	3	順	0.1	2	25	X	1.5	X	2. 纏腳時須注意腳位					
		W3										3. CORE 組合時要靠 BASE, PW3 側					
		W4										4. 三層絕緣線纏腳焊錫時, 剝皮處不能超過 BASE					
		W5															
		W6															
		W7															
		W8															
PAGE / OF / REV. B																	

REMARK 5. 焊錫時須注意不能傷到線圈上的任何線