

Northbrook, Illinois • (847) 272-8800
Melville, New York • (516) 271-6200
Santa Clara, California • (408) 985-2400
Research Triangle Park,
North Carolina • (919) 549-1400
Camas, Washington • (360) 817-5500



CHUNG YI ENTERPRISE CO LTD
MS J CHENG
6F RM 619
5 WU-CHUNG 1ST RD
HEIN CHUNG
TAIPEI TAIWAN

Your most recent listing is shown below. Please review this information and report any inaccuracies to the UL Engineering staff member who handled your UL project.

DUXR2 November 12, 1997
Component - Communication Circuit Accessories

CHUNG YI ENTERPRISE CO LTD E138872 (N)

6F RM 619 5 WU-CHUNG 1ST RD HEIN CHUNG, TAIPEI TAIWAN (A card)

Modular telephone jacks, Series 616E, -M, -W, 616D-4NNN, 616P-4NNN, 623K, 623D-6NNN, 623P-6NNN, 647-10NNN.

Printed circuit board mount jacks, Series 616P, 623P, 9601-4NNN, -6NNN, -8NNN, 9604-4NNN, 9605-4NNN, -6NNN, -8NNN, 9606-6NNN, 9611-4NNN, 9612-6NNN, 9631-6NNN, -8NNN, 9636-4NNN, -6NNN, -8NNN, 9638-4NNN, -6NNN, -8NNN, 9663-6NNN, -8NNN, 9666-6NNN, 9696-4NNN, -6NNN, -8NNN.

Telephone jacks, Models 9601, 9602, 9603, 9604, 9605, 9606, 9607, 9608, 9610, 9611, 9612, 9613, 9614, 9615, 9616, 9617, 9619, 9621, 9623, 9624, 9628, 9629, 9630, 9631, 9631-S, 9631-S2, 9632, 9634, 9636, 9638, 9640, 9644, 9646, 9648, 9650, 9655, 9657, 9659, 9660, 9661, 9662, 9663, 9663-1, 9664, 9666, 9667, 9668, 9669, 9670, 9680, 9690, 9691, 9694, 9695, 9696, 9697, 9698, 9906, 9907, 9909, 9914, 9916, 9917, 9918, 9919, 9926, 9927, 9928, 9929, 9934, 9935, 9936, 9937, 9938, 9939, 9946, 9947, 9948, 9950, 9956, 9957, 9958, 9964, 9966, 9976.

Note: First letter N suffix = No. of contact; Second letter N suffix = Color; Third letter N suffix = Thickness of gold plating.

Reports: June 11, 1991; June 11, 1991; November 10, 1997.

667773001

Underwriters Laboratories Inc.®

(Cont. on B card)
D11/0194600
186

For information on placing an order for UL Listing Cards in a 3 x 5 inch card format, please refer to the enclosed ordering information.

UNDERWRITERS LABORATORIES INC.