

CUSTOMER			PART NUMBER			REV			CONSTRUCTION					SCHEMATIC DRAWING	
			ATS-348S												
BOBBIN:															
BB-EL0802-37															
CORE:															
LM-EL08-05															
GAP:															
TAPE:															
3M#1350W 3M#74 PPI#70100															
ASSEMBLY: 1*1共9片, 組合後, 在CORE 兩邊插入MX-024, 並限制固定。															
FRAME(CLIP): INSULATOR:															
MX-024															
PIN#1 INDICATOR:															
黑點印在LABEL上															
TAP WID Mm	TAP LYR	WID	STR	END	CW/ CCW	WIR SIZ	COA	TUR	CRE PAG	DEN LSN	SIDE WALL				
3M#74	2	W1	2	1	順	0.04	P180 G/F	960	3M#1350W 2.2mm各5片 在兩端	密					
10.2mm	2	W2	4	3	順	0.04	P180 G/F	960	3M#1350W 2.2mm各5片 在PIN#1	密					
PPI#	2	W3							3M#1350W 1.6mm各5片 在PIN#4						
70100		W4													
10.2mm		W5													
		W6													
		W7													
		W8													
REMARKS												1.繞W1時, BOBBIN PIN#1朝外 2.繞W2時, BOBBIN PIN#1朝內 3.插片時, 膠(腹部或稱縫溝)那一面放桌面, 第一片鍍片自BOBBIN上方有凸出那一邊插入 4.貼外層TAPE前先貼LABEL. 5. LABEL要打氣, 貼在腹部 6. CORE兩邊都要裝INSULATOR, 並要左右對齊, 緊靠磁芯, 刷膠固定, 不可鬆動 7. W1與W2的出線, 不可繞在CREEPAGE兩側(同ATS-348)			
PAGE 1 OF 1												REV. A			

REMARK 8: CREEPAGE貼法同ATS-348.