

QMFZ2
Component - Plastics

October 16, 1986

EPOLAB CHEMICAL INDUSTRIES INC
LANE 82 41 CHI-TONG ST , TAIPEI TAIWAN

E105126 (S)
(A card)

Mtl Dsg	Col	Min Thk mm	UL94 Flame Class	Elec	RTI		H W I	H A I	H V T R	D 4 9 5	C T I
					with Imp	w/o Imp					
Epoxy potting compound furnished in two liquid components.											
Eporite 5007A/B	Cream	2.0	94V-0	90	90	90	—	—	—	—	—
		5.0	94V-0	90	90	90	—	—	—	—	—
		10.0	94V-0	90	90	90	—	—	—	—	—
Eporite 5014A/B	BN	2.0	94V-0	90	90	90	—	—	—	—	—
		5.0	94V-0	90	90	90	—	—	—	—	—
		10.0	94V-0	90	90	90	—	—	—	—	—
Eporite 5339A/B	BK	2.0	94V-2	90	90	90	—	—	—	—	—
		5.0	94V-0	90	90	90	—	—	—	—	—
		10.0	94V-0	90	90	90	—	—	—	—	—

Report: October 17, 1986.

743674001

117047

Underwriters Laboratories Inc.™

(Cont. on B card)

D11/0133481